

HISTORY FACILITY PROFILE

WOODLAND PARK CARE CENTER PROVIDER #: 465094 FACILITY BEDS TYPE ACTION: RECERTIFICATION
 3855 SOUTH 700 EAST PHONE NUMBER: (801) 268-4766 TOTAL: 134
 SALT LAKE CITY UT 84106 PARTICIPATION DATE: 07/16/1984 CERTIFIED: 134 TYPE OWNERSHIP: FOR PROFIT - CORPORATION
 STATE'S REGION CODE: 001

COMPLIANCE STATUS: FACILITY MEETS REQUIREMENTS BASED ON AN ACCEPTABLE PLAN OF CORRECTION

RESIDENT CENSUS ON 10/03/2002		LTC ADMISSION/SUSPENSION DATES		TOTAL CERTIFIED BEDS: 134	
-----		-----		-----	
TOTAL:	133	ADMISSION SUSPENDED:	18	18/19	19 ICF/MR
MEDICARE:	45	SUSPENSION RESCINDED:	--	----	-----
MEDICAID:	65			134	
OTHER:	23				

CURRENT SURVEY REVISIT DATES - NONE

PRIOR 3 SURVEY 03/1999	S/S CODE	PRIOR 2 SURVEY 05/2000	S/S CODE	PRIOR 1 SURVEY 07/2001	S/S CODE	CURRENT SURVEY 10/03/2002	S/S CODE	PLAN/DATE OF CORRECT	PROGRAM REQUIREMENTS
		X	D			X P	D	11/30/2002	REQ F0156-INFORM RES OF SERVICES/CHARGES/LEGAL RGTS/ETC REQ F0225-NOT EMPLOY PERSONS GUILTY OF ABUSE REQ F0241-DIGNITY REQ F0248-ACTIVITY PROGRAM MEETS INDIVIDUAL NEEDS REQ F0253-HOUSEKEEPING & MAINTENANCE SERVICES REQ F0278-ACCURACY OF ASSESSMENTS/COORD W/PROFESSIONALS REQ F0279-DEVELOP COMPREHENSIVE CARE PLANS REQ F0281-SERVICES PROVIDED MEET PROFESSIONAL STANDARDS REQ F0309-PROVIDE NECESS CARE FOR HIGHEST PRAC WELL BEING REQ F0322-PROPER CARE & SERVICES FOR RES W/ NG TUBE REQ F0329-DRUG REGIMEN IS FREE FROM UNNECESSARY DRUGS REQ F0333-RESIDENTS FREE FROM SIGNIFICANT MED ERRORS
X	E	X	E	X	E				
X	D			X	E	X P	E	11/30/2002	
X	D	X	D			X P	D	11/30/2002	
X	D								
X	D	X	E						

EDITION OF LSC APPLIED

85 EXIST PRIOR 3 SURVEY 01/1999	85 EXIST PRIOR 2 SURVEY 04/2000	85 EXIST PRIOR 1 SURVEY 07/2001	85 EXIST CURRENT SURVEY 10/08/2002	PLAN/DATE OF CORRECTION
	X	X		
X			X P	10/22/2002
			X N	
X			X P	12/01/2002
	X	X		

LSC DEFICIENCIES - BLDG NO. 01

K0018-CORRIDOR DOORS
 K0038-EXIT ACCESS
 K0050-FIRE DRILLS
 K0056-AUTOMATIC SPRINKLER SYSTEM
 K0061-MAIN SPRINKLER CONTROL
 K0076-MEDICAL GAS SYSTEM
 K0130-OTHER

EDITION OF LSC APPLIED

85 NEW PRIOR 3 SURVEY 01/1999	85 NEW PRIOR 2 SURVEY 04/2000	85 NEW PRIOR 1 SURVEY 07/2001	85 NEW CURRENT SURVEY 10/08/2002	PLAN/DATE OF CORRECTION
	X			
		X		
X			X N	
X			X P	12/01/2002

LSC DEFICIENCIES - BLDG NO. 02

K0018-CORRIDOR DOORS
 K0054-SMOKE DETECTOR MAINTENANCE
 K0056-AUTOMATIC SPRINKLER SYSTEM
 K0061-MAIN SPRINKLER CONTROL
 K0130-OTHER

TYPE OF DEFICIENCY	CURRENT SURVEY	PRIOR 1 SURVEY	PRIOR 2 SURVEY	PRIOR 3 SURVEY
-----	-----	-----	-----	-----
CONDITION	0	0	0	0
REQUIREMENT	3	2	4	5
HEALTH TOTAL	3	2	4	5
LIFE SAFETY CODE	5	3	3	4
LIFE SAFETY CODE + HEALTH	8	5	7	9

COMPLAINT SURVEY INFORMATION

SURVEY DATE	STATUS
-----	-----
03/13/2001	SUBSTANTIATED
07/17/2001	UNSUBSTANTIATED
10/25/2001	UNSUBSTANTIATED
10/03/2002	SUBSTANTIATED

FMS SURVEY INFORMATION

* NO FMS SURVEYS FOR THIS FACILITY

C=DATE OF CORRECTION N=NO DATE GIVEN P=PLAN OF CORRECTION R=REFUSED TO CORRECT W=WAIVED F=FSSES X=DEFICIENT
 COP = CONDITION REQ = REQUIREMENT